	Approved For Release 2002/11/14 : CIA-RDP89B0	0569R000200120071	1 mD/05A
	0020Z 05 JAN 63 SECRET	E	5 OD/OSA
	DIRECTOR: WER		THTEL/OSI
25X1A	KB RLF RDO	TO SECURITY OF THE PROPERTY OF	SKIRMARIMA (P. 1800) M. 1868 (
ONTENAMEN ONTENAMENTE	OSA/TCO (1-2-3-4-5-6-7-8) • PAG	ROUTINE	
	TOR: 0428Z 05 JAN 63		IN 61383
25X1A_		rie er en	ra la conducesco ura musicoste (1) que re concenciado e
<u> </u>			25X1A
25X1A	for info.		
25X1A	2. FROM RE G3210. EVALUATION NO	T COMPLETE BUT	YOU HAVE
	PROBLEMS. FROM START OF MISSION POSITION 3	OR SHOWS HEAVY	OVEREXPOSURE
	INDICATING SLOW SHUTTER. AT FRAME 401 SHUTTER FAILED TO OPEN AND		
	REMAINED CLOSED ON 3R BALANCE OF MISSION. REPEAT THIS APPLIES		
	TO POSITION 3R ONLY.		•

- 3. NEW SUBJ. ON 9L SIDE ON EVERY FRAME THERE IS PIN-HEAD MINUS DENSITY SPOT INDICATING POSSIBLE DIRT ON PLATEN. LOCATION IN LINE WITH INBOARD END OF POSITION INDICATOR AND ABOUT 2 1/2 INCHES FROM SAME.
 - 4. CHIN UP AND HACKLES DOWN.

END OF MESSAGE